## **Asset Report July 2021**

Unless detailed below all assets appear to be in good order, and remain fit for purpose.

Asset	Location	Fault	Remarks
Dog	Village	Damage to part of the "post fixing	Bin is still usable, and appears safe.
litter bir	ı Hall	mechanism" (?) at the top of the bin	. However further investigation of the fault should be undertaken.
Street lights	LFR	Two not working	Due to be replaced by LED units
Old	Bus	Wood work aging, back board	Is still used by some locals for their
Notice	Shelter	warped and coming away. Doors	notices, and the Clerk for some.
Board		missing.	Probably needs replacing.
Village	Village	Some unexplained issue with the	RVMHC is dealing with the issue, but
Hall	Hall Fieldroof		without consultation with RPC.
Litter	Village	Anchoring is broken, and bin lifts	Bin is still usable, and it not a danger to the
Bin	Hall	from ground.	public at this time.

Some of bins could do with a clean on the outside.

Some dog bins (LFR, memorial) could do with the foliage being trimmed back to gain better access to the bin, both for the users, and MSDC refuse collectors.